

F1G. 1




FIG.2A

2107




FIG. 2B





FIG. 3A






FIG. 3C






FIG. 4A


FIG. 48



PSK Fast Hadamard Transform

FIG. 5








FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14 0




FIG. 15




FIG. 16




FIG. 17




FIG. 18





FIG. 19



F16. 20





FIG. 21






FIG. 23

18




FIG. 24A




FIG. 24 B




FIG. 25




FIG. 26




FIG.27